

1. If damaged be sure to refer repairs to CM-101 dealer.



2. Avoid direct sunlight, electro magnetic waves, and heaters!



New to scales?

Here's the do's and don't's!

6.

Don't overload beyond weight limit



3.

Be sure the platter is clear before turning on to avoid calibration damage!



7.

Avoid sudden shock to the scale



4.

Don't place near flammable or corrosive gas!



8.

Always lift scale from the base, not the platter!



5.

Avoid water on the scale, along with humid conditions!



9.



Periodical checks by authorized dealer helps maintain accurate readings!

10.

Remove batteries when not in use

